

RPM	POWER IN	POWER AT END
3000	45.3	49.6
4000	62.7	69.9
5000	77.4	89
5500	82.5	96
6000	N A	100